



TRAFFIC CRASH REPORT

*DENOTES MANDATORY FIELD FOR SUPPLEMENT REPORT

LOCAL REPORT NUMBER*

☒ PHOTOS TAKEN ☐ SECONDARY CRASH		☒ OH-2 ☐ OH-1P ☐ OTHER ☐ PRIVATE PROPERTY		LOCAL INFORMATION		2, 2, 0, 7, 3, 6, 5, 6	
COUNTY* 09		LOCALITY* 1-CITY 2-VILLAGE 3-TOWNSHIP 1		LOCATION: CITY, VILLAGE, TOWNSHIP* City of Fairfield		CRASH DATE / TIME* 10092022 0453	
ROUTE TYPE 1-NORTH 2-SOUTH 3-EAST 4-WEST		ROUTE NUMBER 1		PREFIX 1-NORTH 2-SOUTH 3-EAST 4-WEST		LOCATION ROAD NAME ROSS	
ROUTE TYPE 1-NORTH 2-SOUTH 3-EAST 4-WEST		ROUTE NUMBER 1		PREFIX 1-NORTH 2-SOUTH 3-EAST 4-WEST		REFERENCE ROAD NAME (ROAD, MILEPOST, HOUSE #) 5880	
REFERENCE POINT 1-INTERSECTION 2-MILE POST 3-HOUSE # 3		DIRECTION FROM REFERENCE 1-NORTH 2-SOUTH 3-EAST 4-WEST		ROUTE TYPE IR - INTERSTATE ROUTE(TP) US - FEDERAL US ROUTE SR - STATE ROUTE CR - NUMBERED COUNTY ROUTE TR - NUMBERED TOWNSHIP ROUTE		ROAD TYPE AL - ALLEY AV - AVENUE BL - BOULEVARD CR - CIRCLE CT - COURT DR - DRIVE HE - HEIGHTS HW - HIGHWAY LA - LANE MP - MILEPOST OV - OVAL PK - PARKWAY PI - PIKE PL - PLACE RD - ROAD SQ - SQUARE ST - STREET TE - TERRACE TL - TRAIL WA - WAY	
DISTANCE FROM REFERENCE 1		DISTANCE UNIT OF MEASURE 1-MILES 2- FEET 3-YARDS		ROUTE TYPE IR - INTERSTATE ROUTE(TP) US - FEDERAL US ROUTE SR - STATE ROUTE CR - NUMBERED COUNTY ROUTE TR - NUMBERED TOWNSHIP ROUTE		ROAD TYPE AL - ALLEY AV - AVENUE BL - BOULEVARD CR - CIRCLE CT - COURT DR - DRIVE HE - HEIGHTS HW - HIGHWAY LA - LANE MP - MILEPOST OV - OVAL PK - PARKWAY PI - PIKE PL - PLACE RD - ROAD SQ - SQUARE ST - STREET TE - TERRACE TL - TRAIL WA - WAY	
LOCATION OF FIRST HARMFUL EVENT 1-ON ROADWAY 2-ON SHOULDER 3-IN MEDIAN 4-ON ROADSIDE 5-ON GORE 6-OUTSIDE TRAFFIC WAY 7-ON RAMP 8-OFF RAMP 04		9-CROSSOVER 10-DRIVEWAY/ALLEY ACCESS 11-RAILWAY GRADE CROSSING 12-SHARED USE PATHS OR TRAILS 13-BIKE LANE 14-TOLL BOOTH 99-OTHER / UNKNOWN		MANNER OF CRASH COLLISION/IMPACT 1-NOT COLLISION BETWEEN TWO MOTOR VEHICLES IN TRANSPORT 2-REAR-END 3-HEAD-ON 4-REAR-TO-REAR 5-BACKING 6-ANGLE 7-SIDESWIPE, SAME DIRECTION 8-SIDESWIPE, OPPOSITE DIRECTION 9-OTHER / UNKNOWN		DIRECTION OF TRAVEL 1-NORTH 2-SOUTH 3-EAST 4-WEST	
WORK ZONE RELATED WORKERS PRESENT LAW ENFORCEMENT PRESENT ACTIVE SCHOOL ZONE		WORK ZONE TYPE 1-LANE CLOSURE 2-LANE SHIFT/CROSSOVER 3-WORK ON SHOULDER OR MEDIAN 4-INTERMITTENT OR MOVING WORK 5-OTHER		LOCATION OF CRASH IN WORK ZONE 1-BEFORE THE 1ST WORK ZONE WARNING SIGN 2-ADVANCE WARNING AREA 3-TRANSITION AREA 4-ACTIVITY AREA 5-TERMINATION AREA		CONTOUR 1 1-STRAIGHT LEVEL 2-STRAIGHT GRADE 3-CURVE LEVEL 4-CURVE GRADE 9-OTHER/UNKNOWN	
LIGHT CONDITION 1-DAYLIGHT 2-DAWN/DUSK 3-DARK - LIGHTED ROADWAY 4-DARK - ROADWAY NOT LIGHTED 5-DARK - UNKNOWN ROADWAY LIGHTING 9-OTHER / UNKNOWN 3		WEATHER 1-CLEAR 2-CLOUDY 3-FOG, SMOG, SMOKE 4-RAIN 5-SLEET, HAIL 6-SNOW 7-SEVERE CROSSWINDS 8-BLOWING SAND, SOIL, DIRT, SNOW 9-FREEZING RAIN OR FREEZING DRIZZLE 99-OTHER / UNKNOWN 01		CONDITIONS 1-DRY 2-WET 3-SNOW 4-ICE 5-SAND, MUD, DIRT, OIL, GRAVEL 6-WATER (STANDING, MOVING) 7-SLUSH 9-OTHER/UNKNOWN		SURFACE 1-CONCRETE 2-BLACKTOP, BITUMINOUS, ASPHALT 3-BRICK/BLOCK 4-SLAG, GRAVEL, STONE 5-DIRT 9-OTHER/UNKNOWN	
NARRATIVE On 10/09/2022 at about 4:53 A.M., Unit #1 was traveling northbound on Ross Rd. Unit #1 left the roadway striking the mailbox at 5900 Ross Rd, a fire hydrant, the mailbox at 5880 Ross Rd and then drove through a tree at 5880 before coming to a stop. The owner of the mailbox at 5900 Ross Rd is Daniel Gepfrey, The owner of the fire hydrant is the City of Fairfield, 5350 Pleasant Ave, P/X: The owner of the mailbox and tree at 5880 Ross Rd is William Fette,		Indicate the north direction with an "N" on the compass diagram.		REFER TO OH-2			
CRASH REPORTED DATE / TIME 10092022 0453		DISPATCH DATE / TIME 10092022 0455		ARRIVAL DATE / TIME 10092022 0458		SCENE CLEARED DATE / TIME 10092022 0606	
TOTAL TIME ROADWAY CLOSED 0		OTHER INVESTIGATION TIME 15		TOTAL MINUTES 86		OFFICER'S NAME* M. MAJOR	
TOTAL TIME ROADWAY CLOSED 0		OTHER INVESTIGATION TIME 15		TOTAL MINUTES 86		OFFICER'S BADGE NUMBER* 162	
TOTAL TIME ROADWAY CLOSED 0		OTHER INVESTIGATION TIME 15		TOTAL MINUTES 86		CHECKED BY OFFICER'S NAME* Sgt. B. Carries	
TOTAL TIME ROADWAY CLOSED 0		OTHER INVESTIGATION TIME 15		TOTAL MINUTES 86		CHECKED BY OFFICER'S BADGE NUMBER* 139	
TOTAL TIME ROADWAY CLOSED 0		OTHER INVESTIGATION TIME 15		TOTAL MINUTES 86		REPORT TAKEN BY ☒ POLICE AGENCY ☐ MOTORIST ☐ SUPPLEMENT (CORRECTION OR ADDITION TO AN EXISTING REPORT SENT TO DESP)	

OWNER	UNIT #	OWNER NAME: LAST, FIRST, MIDDLE (SAME AS DRIVER)		OWNER PHONE: INCLUDE AREA CODE (SAME AS DRIVER)	
	01	SINGH, JAGJIVAN			
VEHICLE	OWNER ADDRESS: STREET, CITY, STATE, ZIP (SAME AS DRIVER)				
	4094 ALSACE LN, FAIRFIELD TOWNSHIP, OH, 45011				
EVENT(S)	COMMERCIAL CARRIER: NAME, ADDRESS, CITY, STATE, ZIP				
VEHICLE	LP STATE	LICENSE PLATE #	VEHICLE IDENTIFICATION #	VEHICLE YEAR	VEHICLE MAKE
	OH	SIKNDER	3VWD17A19EM31591699	2014	VOLKSWAGO
VEHICLE	INSURANCE VERIFIED	INSURANCE COMPANY	INSURANCE POLICY #	COLOR	VEHICLE MODEL
	☒	PROGRESSIVE	961534705	SILVER	JETTA
VEHICLE	TYPE OF USE		US DOT #	TOWED BY: COMPANY NAME	
	☐ COMMERCIAL ☐ GOVERNMENT ☐ IN EMERGENCY RESPONSE			FOX	
VEHICLE	INTERLOCK DEVICE EQUIPPED		#OCCUPANTS	HAZARDOUS MATERIAL CLASS # PLACARD ID #	
	☐		01		
VEHICLE	VEHICLE WEIGHT GVWR/GCWR		MATERIAL RELEASED		
	1 - <10K LBS. 2 - 10,001 - 26K LBS. 3 - >26K LBS.		☐		
VEHICLE	UNIT TYPE		PLACARD		
	01				
VEHICLE	# OF TRAILING UNITS		PLACARD		
	00				
VEHICLE	WAS VEHICLE OPERATING IN AUTONOMOUS MODE WHEN CRASH OCCURRED?		AUTONOMOUS MODE LEVEL		
	02		0		
VEHICLE	SPECIAL FUNCTION		VEHICLE WEIGHT GVWR/GCWR		
	01		1 - <10K LBS. 2 - 10,001 - 26K LBS. 3 - >26K LBS.		
VEHICLE	CARGO BODY TYPE		HAZARDOUS MATERIAL CLASS # PLACARD ID #		
	01				
VEHICLE	VEHICLE DEFECTS		HAZARDOUS MATERIAL CLASS # PLACARD ID #		
	01				
VEHICLE	NON-MOTORIST LOCATION AT IMPACT		HAZARDOUS MATERIAL CLASS # PLACARD ID #		
	01				
VEHICLE	ACTION		HAZARDOUS MATERIAL CLASS # PLACARD ID #		
	03				
VEHICLE	CONTRIBUTING CIRCUMSTANCES		HAZARDOUS MATERIAL CLASS # PLACARD ID #		
	11				
VEHICLE	SEQUENCE OF EVENTS		HAZARDOUS MATERIAL CLASS # PLACARD ID #		
	08				
VEHICLE	NON-COLLISION		HAZARDOUS MATERIAL CLASS # PLACARD ID #		
	09				
VEHICLE	COLLISION WITH FIXED OBJECT		HAZARDOUS MATERIAL CLASS # PLACARD ID #		
	07				
VEHICLE	STUCK		HAZARDOUS MATERIAL CLASS # PLACARD ID #		
	08				
VEHICLE	FIRST HARMFUL EVENT		HAZARDOUS MATERIAL CLASS # PLACARD ID #		
	2				
VEHICLE	MOST HARMFUL EVENT		HAZARDOUS MATERIAL CLASS # PLACARD ID #		
	5				

LOCAL REPORT NUMBER	
22073656	
DAMAGE	
DAMAGE SCALE	
1 - NONE 3 - FUNCTIONAL DAMAGE	
2 - MINOR DAMAGE 4 - DISABLING DAMAGE	
9 - UNKNOWN	
DAMAGED AREA(S) INDICATE ALL THAT APPLY	
☐ - NO DAMAGE [0] ☐ - UNDERCARRIAGE [14]	
☐ - TOP [13] ☒ - ALL AREAS [15]	
☐ - UNIT NOT AT SCENE [16]	
INITIAL POINT OF CONTACT	
0 - NO DAMAGE 14 - UNDERCARRIAGE	
1-12 - REFER TO UNIT DIAGRAM 15 - VEHICLE NOT AT SCENE	
13 - TOP 99 - UNKNOWN	
TRAFFIC	
TRAFFICWAY FLOW	TRAFFIC CONTROL
1 - ONE-WAY	1 - ROUNDABOUT 4 - STOP SIGN
2 - TWO-WAY	2 - SIGNAL 5 - YIELD SIGN
	3 - FLASHER 6 - NO CONTROL
# OF THROUGH LANES ON ROAD	RAIL GRADE CROSSING
2	1 - NOT INVOLVED
	2 - INVOLVED-ACTIVE CROSSING
	3 - INVOLVED-PASSIVE CROSSING
UNIT / NON-MOTORIST DIRECTION	
1 - NORTH 5 - NORTHEAST	
2 - SOUTH 6 - NORTHWEST	
3 - EAST 7 - SOUTHEAST	
4 - WEST 8 - SOUTHWEST	
9 - OTHER / UNKNOWN	
UNIT SPEED	DETECTED SPEED
35	1 - STATED / ESTIMATED SPEED
	2 - CALCULATED / EDR
	3 - UNDETERMINED
POSTED SPEED	
25	

HSY8306 OH1M 1/19 [760-1500]

LOCAL REPORT NUMBER 22-073656	REPORTING AGENCY Fairfield Police Department	DATE OF ACCIDENT 10/9/22
IN COUNTY OF Butler	ACCIDENT LOCATION 5880 ROSS RD	

The diagram is a hand-drawn sketch on a grid background. It shows a vertical road labeled "ROSS RD" with an arrow pointing upwards. To the right of the road, there are two rectangular property lots labeled "5880" and "5900". A dashed line runs vertically between the road and the properties. Along this dashed line, there are four rectangular boxes, each containing a vertical line and a triangle at the top. From top to bottom, the features are: a "Tree" (represented by a circle with a cross), a "Mailbox", a "Fire Hydrant" (represented by a hexagon with a cross), and another "Mailbox". Arrows point from the labels to their respective symbols. In the bottom left corner, the text "NOT TO SCALE" is written.

OFFICER'S SIGNATURE M. MAJOR	BADGE NO. 162
---------------------------------	------------------